

This Page Is Inserted by IFW Operations
and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

**As rescanning documents *will not* correct images,
please do not report the images to the
Image Problem Mailbox.**

Applicant : Patrizio Vinciarelli
Serial No. : 10/785,465
Filed : February 24, 2004
Page : 7 of 7

Attorney's Docket No.: 00614-144001

REMARKS


No changes have been made to the claims, leaving claims 1-70 pending in the application.

The reference designations S1-S4 used to identify the switches in Figures 3, 4, and 6 have been changed to SW1-SW4 in Figs. 3, 4, and 6 and in the specification to avoid duplication with reference designations S1, S2, and S3 identifying the secondary windings in Fig. 6. No new matter has been added. Formal drawings incorporating the amendments to Figs. 3, 4, and 6 are being submitted herewith in the event that the examiner approves of the amendment.

Applicant asks that all claims be examined in view of the amendment to the claims.

No fees are believed to be due however, please apply any charges or credits to deposit account 06-1050.

Respectfully submitted,


Andrew T. D'Amico
Reg. No. 33,375

Date: June 4, 2004
Fish & Richardson P.C.
45 Rockefeller Plaza, Suite 2800
New York, New York 10111
Telephone: (212) 765-5070
Facsimile: (212) 258-2291



Annotated

30




Fig 3

Prior Art

Annotated




Fig 4

Annotated




Fig. 6

250